

CASH BILL



鋒達汽車維修服務 HONDAI MOTOR SERVICE

Blk 3012 Bedok Ind. Park E #01-2046 Singapore 489978.
(Bedok North Ave. 4) Tel: 6443 8631 Fax: 6448 5177
Reg. No.: 52813887A



No. 20776

M/s

SJN8603R

Date:

11/10/22

Quantity	Description	Amount
8PC	REAR BEARING	\$700
1SET	REAR BRACE-SHOE	
4PC	TYRES.	
4L	Full Sun Engine oil	
1PC	JIL filter	
	Service Package	

Goods received in good order & condition.

TOTAL:

\$700/-

Authorised Signature

HONDAI MOTOR SERVICE