



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KHOR SAW THENG			Ref: CS3/ASM22011277/Dvy3m4 Date: 30/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3190P	Veh. Inspected	GX 6959K	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M04EGU	Excess (\$)	0.00	
Assign From	KHOR SAW THENG	Assign Date	10/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150 D	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	JTFUF34Y903002627	Colour	BLUE	
Odometer	521902 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14	WINDFORCE	6 mm	
L/H Front Tyre	185 R14	WINDFORCE	6 mm	
R/H Rear Tyre	155 R12	KAPSEN	5 mm	
L/H Rear Tyre	155 R12	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/11/2022	Inspection Date	27/12/2022	
Survey held at	SOON LEE CHOON AUTO SERVICES BLK 5032 ANG MO KIO IND.PARK 2 #01-283 . SINGAPORE 569535			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	