



BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

 **6744 0777**

 **6744 2377**

Date: **10th Nov 2022, Thursday**

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16

Singapore 079120

Tel: 6419 3000

By EMAIL: admin-a@lkkauto.com.sg

Dear Sir / Madam,

REF: Your Insured Vehicle SMW 8722Y

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SMA 4713R & SMW 8722Y ON 09/11/2022
ALONG WOODLANDS AVENUE 6 @ 1308 HRS.**

Our client's vehicle – SMA 4713R was damaged in the above accident.

A copy of the Singapore Accident Statement report filed is enclosed.

As a result of the accident, the vehicle has been damaged. Before we proceed to repair the damaged vehicle, **please assist to arrange surveyor to conduct the survey of the vehicle within 2 working days.**

Please be informed that the said vehicle can be inspected at:

Name of Workshop: **Best Solution Autocare Pte Ltd**

Address: **53 Ubi Avenue 1 #03-01 Paya Ubi Industrial Park S(408934)**

Contact Person: **Ms LEE**

Telephone No: **6744 0777**

Fax No: **6744 2377**

Please note that if we do not receive any reply from you within the stipulated timeline, you will be deemed to have waived your rights to a pre-repair inspection. In view of that, we shall proceed to repair the vehicle without further reference to you.

Thank You

BEST SOLUTION AUTOCARE PTE LTD