TP - Budget Direct Vonon

FONG MOTORS 1 Kaki Bukit Ave 6 #01-27/45 AutoBay@ Kaki Bukit, Singapore 417883 Tel: 6748 5648, Email: fongmotors@gmail.com **Estimate of Cost of Repairs** Date 22-Nov-2022 Vehicle No. SND5429C Model Honda Civic SIR CHASSIS/ENG# JHMEK4550WS003005 PARTS S/N Item Quantity **Unit Price** Amount Tail Gate Emblem \$38.50 \$38.50 Tail Gate \$681.20 \$681.20 * Tail Gate Lock \$86.50 \$86.50 Tail Gate Reflector · New \$208.30 \$416.60 End Panel \$584.00 \$584.00 -End Panel Gamish \$108.20 \$108.20 RH could Tail Lamp \$381.20 \$762.40 285. Tail Gate Weatherstrip 8 \$137.70 \$137.70 Rear Bumper Del 9 \$684.10 \$684.10 antic 10 Head Lamp 2 \$542.80 \$1,085.60 Head Lamp Lower Bracket New 11 2 \$38.90 \$77.80 + Front Bumper 12 Deh \$649.80 1 \$649.80 and d. 13 Radiator Grille \$179.30 \$179.30 / Nem 14 Bumper Bracket \$67.20 \$134,40 15 Top Panel Puis \$192,20 \$192.20 Sub-total 1 \$5,818.30 NETT ITEMS S/N Item Quantity **Unit Price** Amount Front Bumper Clip 1 Set \$60.00 30 \$60.00 Rear Bumper Clip 1 Set \$60.00 New End Panel Gamish Clip \$60.00 - 10 1 Set \$60.00 Not New 4 Rear Sensor \$150.00 \$300.00 * Sub-total 2 \$480.00 LABOUR 1200 To remove and replace parts and knock front and rear damaged portion \$1,400.00 To spray front bonnet, bumper and rear affected portion \$1,500.00 100 To conduct wiring checks \$80.00 60 To remove and replace reverse sensors \$100.00 To remove and refit upholstery to facilitate repairs \$100.00 6 Tuff kote \$100.00 Labour Total \$3,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

.



Parts & Labour Total \$9,578.30

total: 5620.96 HS: 4.5K.

3838.70 3070.96