



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS/LPC22007925/Rny3-1

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS/LPC22007925/Rny3~~

Date: ~~18/08/2022~~ 09/11/2022

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNG 5488R	Veh. Inspected	SG 5062B
Policy No.		Coverage (\$)	0.00
Claim No.	22/22/22/VP05/026121	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	18/08/2022 09/11/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/08/2022	Inspection Date	18/08/2022
Survey held at	3 Yio Chu Kang Crescent road		
Repairer	SBS TRANSIT LTD (HQ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.