



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2207486

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 05/12/2022
Reference CS3/III22005648/Tvy3e2-1
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SKJ 5858B
Insured Veh. SH 109D
Claim No. MFL2022D0003119
Policy No. D19MFL0000003_03
Accident Date 11/06/2022
Inspection Date 14/06/2022

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Less: Pre-Repair Survey Fee (Invoice.AC2203924 dated 24/06/2022)	-120.00
Subtotal	130.00
GST (7%)	9.10
Grand Total	139.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM