



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22006050/Eny3e2-1	
			Date: 14/11/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHF 283Z	Veh. Inspected	FBJ 3822Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/22/2031	Excess (\$)	0.00
	Assign From	ASHLENE LEE	Assign Date	10/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA JUPITER	c.c	134
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	MH355S004EK130851	Colour	RED
	Odometer	75732 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	80-90-17	DUNLOP	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	90/80-17	DUNLOP	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/06/2022	Inspection Date	27/06/2022
	Survey held at	RIGHT CLICK AUTOWORKS PTE LTD 7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	