

Main Office:

 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:

 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

 Tel: (65) 6272 3892
 Fax: (65) 6270 8314

 Co. Reg. 198904033G
 GST Reg. M2-008864-2

ESTIMATE

SOMPO INSURANCE (S) PTE LTD
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623.

 Page : 1
 Veh No : SLK9725H
 Model : TOYOTA ALTIS
 DOA : 8-Nov-22
 Incharge : BILLY
 Code : CD0032

No	Description	Qty	U.Price	Amt \$
LIST ITEMS				
1	BOOT LID ✓ DD	1	\$ 852.90	\$ 852.90 ✓
2	BOOT LID HINGE RH & LH X NN	2	\$ 68.00	\$ 136.00 X
3	BOOTLID LOGO ✓ NEC	1	\$ 66.90	\$ 66.90 ✓
4	BOOT LID EMBLEM - COROLLA ✓ NEC	1	\$ 45.00	\$ 45.00 ✓
5	BOOT LID EMBLEM - ALTIS ✓ NEC	1	\$ 45.00	\$ 45.00 ✓
6	BOOT LID CHROME MOULDING X NN	1	\$ 233.70	\$ 233.70 X
7	BOOT LID REFLECTOR RH & LH ✓ CUT	2	\$ 377.60	\$ 755.20 ✓
8	BOOT LID LOCK → ✓ BT	1	\$ 382.50	\$ 382.50 210 ✓
9	BOOT LID WEATHERSTRIP ✓ TN	1	\$ 185.00	\$ 185.00 ✓
10	TAILLAMP ASSY RH & LH ✓ BR	2	\$ 410.80	\$ 821.60 ✓
11	TAILLAMP PANEL RH & LH (REPAIR) X R	2		\$ -
12	REAR END PANEL ✓ DD	1	\$ 727.50	\$ 727.50 655 ✓
13	REAR END PANEL TOP GARNISH ✓ CRU	1	\$ 240.00	\$ 240.00 ✓
14	SPARE WHEEL PANEL (REPAIR) X R	1		\$ -
15	BOOT LID KEYLESS ✓ BR	1	\$ 208.00	\$ 208.00 ✓
16	REAR BUMPER ✓ DD	1	\$ 602.60	\$ 602.60 ✓
17	REAR BUMPER REINFORCEMENT ✓ DD	1	\$ 432.50	\$ 432.50 ✓
18	REAR BUMPER BRACKET RH & LH ✓ BR	2	\$ 65.00	\$ 130.00 ✓
19	REAR BUMPER RETAINER RH & LH X NN	2	\$ 95.00	\$ 190.00 X
20	REAR BUMPER CLIPS ✓ NEC	10	\$ 5.00	\$ 50.00 30 Nett ✓
LIST TOTAL S\$				\$ 6,104.40
25% DISCOUNT S\$				\$ 1,526.10
Supplementary Spare tyre board \$288.40 ✓ TN				\$ 4,578.30
5538.10 -25% 4153.57				
30				
SPECIAL NET ITEMS:				
1	REVERSE SENSOR ✓ Shorted	1	\$ 200.00	\$ 200.00 ✓
SPECIAL NET TOTAL S\$				\$ 200.00
nett - 230				

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

LABOUR:

1	TO CUT / WELD REAR END PANEL.KNOCK & STRAIGHTEN TAILLAMP PANELS, SPARE WHEEL PANEL, REAR BODY MEMBERS. REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION		\$	✓	800.00
2	SPRAY PAINT BOOT LID, REAR END PANEL, TAILLAMP PANELS , SPARE WHEEL PANEL, REAR BUMPER, REAR FENDER RH & LH		\$	✓	1,000.00
3	REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM GARNISH,COVERING		\$		60.00 ✓
4	REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION		\$		60.00 30
5	RUST PROOF AFFECTED AREAS	1920	\$		60.00 30
	LABOUR TOTAL S\$	6303.57	\$		1,980.00

L/S - 5042.85
= 5050

Steve (LKK)
11/11/22
Without Prejudice
L/S
Resurvey After Spray
6 days

	\$	6,758.30
NON-TAX AMOUNTS	\$	473.08
GST @ 7%	\$	7,231.38
AMOUNT DUE		

[Signature]

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: