



Not Authorized
 61 Pay @ 5300/-
 Recovery After Paint
 6 days

**ESTIMATE TO REPAIR**

VEHICLE NO. : SLV 6509 C
 MAKE : KIA
 MODEL : CERATO K3 1.6A SUNROOF
 YEAR : 2018
 CHASSIS NO : KNAFZ411MJ5767654

SURVEYOR NAME :
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 10-Nov-22
 DATE OF ACCIDENT : 08-Nov-22
 THIRD PARTY REF : SE 9339 M
 THIRD PARTY REF : SOMPO INSURANCE (S) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear bumper 639			<i>inc/ agent</i>	639.00
1 pc	Rear bumper reinforcement			<i>cm</i>	313.00
2 pcs	Rear bumper retainer			<i>m</i>	50.00
10 pc	Rear bumper clips		\$ 25.00	<i>m</i>	30.00
1 pc	Rear end panel		\$ 3.00	<i>m</i>	274.00
1 pc	Rear end panel garnish			<i>cm</i>	58.00
1 pc	Front bumper 639			<i>inc/ agent</i>	639.00
1 pc	Front bumper reinforcement			<i>m</i>	496.00
1 pc	Front bumper retainer			<i>m</i>	50.00
10 pc	Front bumper clips		\$ 25.00	<i>m</i>	30.00
1 pc	Front grille		\$ 3.00	<i>cm</i>	328.00
2 pcs	Head lamp 2208		\$ 2,209.00	<i>n/s 61</i>	4,418.00
	Less 10%				7,325.00
					732.50
					6,592.50
1 set	Rear bumper sensor	S/N		<i>h</i>	200.00
1 pc	Front no plate	S/N		<i>m</i>	40.00
	To putty & spray paint			<i>800</i>	1,200.00
	Paint treatment			<i>(Bill)</i>	600.00
	To check front wiring & focus head lights			<i>300</i>	35.00
	To anti rust			<i>m</i>	80.00
	Labour charge			<i>800</i>	800.00
TG/ZX	TOTAL				\$ 9,547.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520693 Fax: 65-64598127 Email: edmund@LTM.sg
 Co. Reg No. 199397277D GST Reg No. M2-0018006-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd



SUPPLYMENTARY TO REPAIR

VEHICLE NO. : SLV 6509 C
MAKE : KIA
MODEL : CERATO K3 1.6A SUNROOF
YEAR : 2018
CHASSIS NO : KNAFZ411MJ5757654

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :
DATE : 15-Nov-22
DATE OF ACCIDENT : 08-Nov-22
THIRD PARTY REF : SE 9339 M
THIRD PARTY REF : SOMPO INSURANCE (S) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear boot lock				\$ 101.00
	Less 10%				\$ 10.10
1 pc	rear bumper spoiler	S.Nett			\$ 680.00
1 pc	rear bumper top protection film	S.Nett			\$ 150.00
TG/VL	TOTAL				\$ 920.90