



1 of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Ref: CS/ASM22011340/Uwp3

Date: 11/11/2022

Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SCP 3737T	Veh. Inspected	SFM 1834P
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04ELP	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	11/11/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/11/2022	Inspection Date	11/11/2022
Survey held at	BLUWEL RENT-A CAR PTE LTD BLK 1 KAKI BUKIT AVE 6 BLK C #01-56 AUTOBAY @KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--