

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

FRE-REFAIR INSPECTION REFORT						
	MS FIRST CAPITA	L INSURANCE LTD	I	Ref:	CS3/FCI22009129/Eny3e2	
	36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877		I	Date:	29/09/2022	
			(Code:	FCI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	PC 5189B	Veh. Inspected		FBS 8681H	
	Policy No.	D-22099590MFBP/1	Coverage (\$)		0.00	
	Claim No.	D22002645MFBP	Excess (\$)		0.00	
	Assign From	AINI BINTE	Assign Date		16/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA FORZA	c.c		329	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	MLHNF097XM5019388	Colour		RED	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	140/70-14	BRIDGESTONE		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/70-15	BRIDGESTONE		4 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUS	CLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information						
	Accident Date	21/08/2022	Inspect Date / T	ime	16/09/2022 (01:25 PM)	
	Survey held at	SPEEDWAY MOTOR PL				
		36 TOH GUAN ROAD EAST #01-32 ENTERPRISE HUB SINGAPORE 608580				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$20,000.00					

Report Ref No. CS3/FCI22009129/Eny3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser