

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM22011349/Tpa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	31/01/2023	
	ATTN:YVONNE			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHA 7057R	Veh. Inspected		SJN 393Z	
	Policy No.	P2465679	Coverage (\$)		0.00	
	Claim No.	S2M04EJG	Excess (\$)		0.00	
	Assign From		Assign Date		11/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI LANCER 2.0	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	JMYSTCY4A8U004933	Colour		GREY	
	Odometer	183356 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	MICHELIN		6 mm	
	L/H Front Tyre	225/40 R18	MICHELIN		6 mm	
	R/H Rear Tyre	225/40 R18	MICHELIN		6 mm	
	L/H Rear Tyre	225/40 R18	MICHELIN		6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	08/11/2022	Inspection Dat	е	14/11/2022	
	Survey held at	d at AP AUTOMOTIVE SERVICES PTE LTD				
		9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		10 Worl	king Days	