

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 14 Nov 2022

**Preliminary Advice**

Vehicle No	: SMF6803A	Accident Date	: 07/11/2022
Make	: TOYOTA COROLLA ALTIS	Policy No.	: DMPCSNW00006952200
Assignment Date	: 11/11/2022	Excess	: S\$0.00
Date of Inspection	: 14/11/2022	Est. Duration of Repair	: 07 DAYS
Inspection At	: DING AUTO PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,774.44
Revised Amount	:S\$	4,199.44
Check Items (Estimated)	:S\$	4,045.00
Total	:S\$	8,244.44

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	12,000.00
COE / PARF Rebate	:S\$	3,038.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,962.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.