

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001987245	Date of Loss:	07/11/2022
Vehicle Reg. No.:	SNF4151Z	Driveable?	
Driver Age/Info:	41 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SHREE KARTHIGESAN	Contact No:	+6592381093
Driver:	SHREE KARTHIGESAN		
Make/Model:	TOYOTA ALPHARD, 2.4 (A)	Vehicle Reg. Date:	13/11/2013
Vehicle Colour:	Silver		
Engine No:	2AZJ033497	Chassis No:	JTEGD21H608302408
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9		
Description of Accident/Loss	REFER TO GIA REPORT		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	5,275.40
Miscellaneous Items	0.00
Labour	1,880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,155.40
+ GST 7.00% (S\$)	500.88
Nett Amount (S\$)	7,656.28

This claim is handled by: JANICE CHANG SIEW YIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Nov 2022)
Parts: M1-MPV TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SNF4151Z/11/11/2022 14:34
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRT NUMBER PLATE <i>Grille</i>	0	0.00	*35.00 FS	✓
2	1		*FRT BUMPER <i>destined</i>	0.00	0.00	*220.00 F	✓
3	10		*FRT BUMPER CLIP <i>Heu</i>	0.00	0.00	*10.00 F	✓
4	1		*FRT BUMPER LOWER GRILLE <i>HH</i>	0.00	0.00	*90.00 F	X
5	2		*FRT BUMPER RETAINER <i>Src</i>	0.00	0.00	*90.00 F	X
6	1		*FRT BUMPER REINFORCEMENT <i>Reinft</i>	0.00	0.00	*180.00 F	✓
7	1		*FRT BUMPER SPONGE ?	0.00	0.00	*70.00 F	?
8	1		*FRT BUMPER CHROME ?	0.00	0.00	*120.00 F	?
9	1		*FRT PARKING SENSOR (RH) <i>Dom</i>	0.00	0.00	*160.00 F	✓
10	1		*FRT GRILLE ?	0.00	0.00	*240.00 F	?
11	1		*FRT GRILLE EMBLEM <i>cut? cut</i>	0.00	0.00	*70.00 F	✓
12	1		*FRT BONNET <i>bt</i>	0.00	0.00	*240.00 F	✓
13	2		*FRT BONNET HINGE <i>1/2</i>	0.00	0.00	*90.00 F	✓
14	1		*FRT BONNET CHROME <i>Src</i>	0.00	0.00	*180.00 F	X
15	9		*FRT BONNET INSULATOR CLIPS <i>HH</i>	0.00	0.00	*9.00 F	X
16	1		*FRT HEADLAMP(RH) ?	0.00	0.00	*580.00 F	?
17	1		*FRT FENDER(RH) <i>run</i>	0.00	0.00	*320.00 F	X
18	1		*FRT FENDER INNERSHIELD(RH) <i>LH turn</i>	0.00	0.00	*140.00 F	✓
19	10		*FRT FENDER INNERSHIELD CLIP <i>LH Heu</i>	0.00	0.00	*10.00 F	✓
20	1		*FRT SUPPORT PANEL <i>hey fey</i>	0.00	0.00	*580.00 F	X
21	1		*FRT BRACE PANEL <i>1/2</i>	0.00	0.00	*70.00 F	?
22	1		*AIRCON CONDENSER <i>1?</i>	0.00	0.00	*550.00 F	?
23	1		*RADIATOR ?	0.00	0.00	*580.00 F	?
24	1		*RADIATOR AIR GUIDE (RH) <i>HH</i>	0.00	0.00	*150.00 F	X
25	1		*RADIATOR TOP BRACKET ?	0.00	0.00	*15.00 F	?

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 4,799.00
+ Margin on L,N Items 10.00% (\$\$) 476.40

Total Parts (\$\$) 5,275.40

Sng Ah Tee Motor & Panel Service Pte Ltd/SNF4151Z/11/11/2022 14:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	New	850.00 600/-
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New	900.00 600/-
3	TO REFILL AIRCON GAS	New	100.00 80/-
4	TO CHECK WIRING	New	30.00 20/-
Gross Labour Cost (S\$)			1,880.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SNF4151Z/11/11/2022 14:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >