

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0984/2022/EQ

16-Dec-22

CHANG

1 of 1

SFM 898 L

AUDI A5 SPORTBACK 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO DISLodge AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF REINFORCEMENT BEAM BRACKET. S/N	\$ 480.00	✓ ✓
Parts			
1	FRONT REINFORCEMENT BEAM BRACKET - LH 1 Best	\$ 254.00	✓ 203.20
GRAND TOTAL		\$ 734.00	

For Premium Automobiles Pte Ltd

Adrian Ling
Remerged.



Authorised Signature

+ add 1 working day for the partial dislodging of the lock carrier so as to facilitate the removal of the reinforcement beam bracket LH.

Sl.S.