

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0984/2022/EQ 16-Dec-22 CHANG 1 of 1 SFM 898 L AUDI A5 SPORTBACK 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO DISLodge AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF REINFORCEMENT BEAM BRACKET. S/N	\$ 480.00	✓
Parts			
1	FRONT REINFORCEMENT BEAM BRACKET - LH 1 <i>Best</i>	\$ 254.00	✓
GRAND TOTAL		\$ 734.00	

For Premium Automobiles Pte Ltd

*Adrian Ling
Remerged.*



Authorised Signature

+ add 1 working day for the partial dislodging of the lock carrier so as to facilitate the removal of the reinforcement beam bracket LH.

Slg.