

Our Job Ref No : 305532126
Date : 07/10/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Taufikh
Vehicle Reg No. : SHB3755E

Fax :

03.10.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **INCOME** -- **SJT6526L**
 2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,339.78
 - (b) Labour Charges \$1,230.00
 - Total for Part-By-Part Repair Cost \$2,569.78**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$0.00
 3. Estimated normal period for repairs: 2 working days.
 4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
 5. Thank you for your assistance.

Signature :
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156
- We confirm the estimates and finalized amount

Signature :
Name : Taufikh
Date : 16/11/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305532126
 REGN NO : SHB3755E
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 30.10.2020
 DATE/TIME IN : 04.10.2022 10:05
 ACCIDENT DATE : 03.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60
0003	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0004	04-01-0104-2270-G	EMBLEM-HYBRID	1	24.30	20.00	19.44
0005	04-01-0104-2271-G	EMBLEM-IONIQ	1	31.30	20.00	25.04
0006	28-01-0103-0009-A	REAR BOOT LOGO CCTPL	1	30.00	10.00	27.00
0007	28-01-0103-0010-A	REAR BOOT TEL NUMBER CCTP	1	40.00	10.00	36.00
0008	28-01-9999-2035-A	ZIG BOOK NOW APP LOGO REA	1	30.00	10.00	27.00
0009	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00
0010	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1	180.00	10.00	162.00
0011	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	55.00	10.00	49.50
0012	04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64
0013	04-01-0104-2544-G	CAP-RR HOOK	1	98.80	20.00	79.04

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305532126
REGN NO : SHB3755E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2020
DATE/TIME IN : 04.10.2022 10:0
ACCIDENT DATE : 03.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,339.78

JOB NATURE

0000 PB	PANEL BEATING SHB3755E- TP	350.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 20-204	REMOVE/REFIX REVERSE SENSOR	30.00
0003 L	RENEW ADVERTISEMENT STICKER	350.00

SUB-TOTAL : 1,230.00

TOTAL : 2,569.78


Loke Wei Yang

MVA NAME & SIGNATURE

DATE : 7/10/22

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :