

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 21 Nov 2022

Preliminary Advice

Insured Vehicle No : SLL9020C
TP Vehicle No : SNA2643K Accident Date : 13/11/2022
Make : MERCEDES-BENZ E200 Assignment Date : 15/11/2022
Date of Inspection : 15/11/2022 Est. Duration of Repair : 3
Inspection At : NINETEEN AUTOWERKS PTE LTD - WOODLANDS (HQ)
39 WOODLANDS CLOSE, MEGA@WOODLANDS #01-24
SINGAPORE 737856

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,759.04
Revised Amount	:S\$	2,506.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,506.60
Lump Sum Repair	:S\$	2,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	158,000.00
COE / PARF Rebate	:S\$	70,309.00
Salvage Value	:S\$	
Margin for Repair	:S\$	87,691.00

Remarks

- The vehicle is economical for repair
- The vehicle is not economical for repair
- Part-by-Part repair
- Lump Sum repair

- The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.