

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Xiao Tong

Estimate : TP22-136

Date : 10/11/2022
Vehicle Num. : SJY7278U
Make/Model : Kia Cerato Forte-2010
Chassis/Eng# : KNAFW611MA5278828/G4FCAH226944
Accident Date : 07/11/2022
Claim No. :
Reference :
Policy No. : (21/01/2023)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 ps	Rear Boot Lid <i>Dented</i>		974.00 ✓
2.	2 pcs	Rear Boot Lid Hinge L/R <i>broken</i>	98.00	196.00 +
3.	1 pc	Rear Boot Lamp RH		356.00 +
4.	1 pc	Rear 'Kia' Logo <i>new</i>		58.00 ✓
5.	1 pc	Rear Boot Mechanism lock <i>end</i>		181.00 ✓
6.	1 pc	Rear Boot Weatherstrip <i>lit</i>		115.00 ✓
7.	2 pcs	Rear Lamp Assy L/R <i>new</i>	369.00	738.00 +
8.	1 pc	Rear Bumper Assy <i>dented</i>		810.00 ✓ <i>689</i>
9.	1 set	Rear Bumper Clips <i>new</i>		30.00 ✓
10.	1 pc	Rear Reverse Sensor <i>new</i>		241.00 ✓
11.	1 pc	Rear Bumper Lower Spoiler <i>dented</i>		325.00 ✓
12.	1 pc	Rear No Plate Lamp <i>new</i>		45.00 +
13.	1 pc	Rear Bumper Inner Sponge <i>crushed</i>	370.8	198.00 ✓
14.	1 pc	Rear Bumper Reinforcement <i>crushed</i>		372.00 ✓
15.	1 pc	Rear End Panel <i>Dented</i>	3337.20	418.00 ✓
16.	1 pc	Rear Bumper Reflector Lamp RH <i>new</i>		42.00 ✓
17.	1 pc	Rear Exhaust Silencer Box Assy <i>new</i>		686.00 +
18.	1 pc	Rear End Panel Inner Top Garnish <i>dented</i>		65.00 ✓
19.	1 pc	Rear Spare Tyre Panel <i>Repair</i>		896.00 +
List Total S\$:				6,746.00
10.00% Discount S\$:				674.60
				6,071.40

SPECIAL NETT ITEMS :				
1.	1 pc	Rear No. Plate w/frame <i>crushed</i>	60	75.00 ✓ <i>60</i>
Special Nett Total S\$:				75.00

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP22-136

Date : 10/11/2022

Vehicle Num. : SJY7278U

Make/Model : Kia Cerato Forte-2010

Chassis/Eng# : KNAFW611MA5278828/G4FCAH226944

Accident Date : 07/11/2022

Claim No. :

Reference :

Policy No. : (21/01/2023)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

To remove, repair and replaced damaged bodyparts,
realign bodyworks & where consistent to the accident

1,800.00 *SW*

To remove, rearrange electrical wirings, check lighting

120.00 *30*

To remove, instal rear exhaust silencer box

150.00 *X*

To putty & respray painting of boot lid, bumper,
end panel, tyre panel.

1,500.00 *SW*

Labour Total S\$:

3,570.00

Adrian Lj
L/S 11/11/22
06 days

total : 5027.20

L/S : 4K ✓

Total S\$: 9,716.40

=====

[Signature]
SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: