

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Xiao Chan

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFC 6767 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE OF LHS FRONT DOOR.	S/N \$	280.00	✓
(2)	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS.	S/N \$	400.00	✓ <i>sl.s.</i>
3	TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	800.00	500
4	TO RESPRAY LHS WING MIRROR COVER, LHS FRONT DOOR, LHS REAR DOOR, TWO DOOR HANDLES AND LHS REAR FENDER.	\$	3,500.00	1450 Mirror 150 Handle x 2 : 200 Door 550 Fender 550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 5,172.00	1450

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFC 6767 U

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT EXTERIOR WING MIRROR MOUNTING - LH <i>at</i>	1	\$	3,069.00	✓	<i>fls.</i>
2	FRONT WING MIRROR CAP - LH <i>cracked</i>	1	\$	348.00	✓	
3	FRONT WING MIRROR GLASS - LH <i>crack</i>	1	\$	1,298.00	✓	
4	FRONT DOOR HANDLE - LH <i>Repair</i>	1	\$	389.00	+	
5	FRONT DOOR HANDLE CHROME TRIM PLATE - LH <i>new</i>	1	\$	109.00	+	
6	FRONT DOOR PANEL CHROME CAP - LH UPPER	1	\$	100.00	+	
7	FRONT WINDOW GUIDE TRIM STRIP - LH <i>at</i>	1	\$	287.00	✓	
8	FRONT WINDOW GUIDE - LH <i>new</i>	1	\$	542.00	+	
9	FRONT DOOR WINDOW - LH <i>at</i>	1	\$	365.00	✓	<i>fls.</i>
10	REAR DOOR HANDLE - LH <i>Repair</i>	1	\$	389.00	+	
11	REAR DOOR HANDLE CHROME TRIM PLATE - LH <i>new</i>	1	\$	109.00	+	
12	REAR DOOR PANEL CHROME CAP - LH UPPER <i>new</i>	1	\$	100.00	+	
13	SUNDRIES <i>?</i>		\$	300.00	?	
TOTAL SPARE PARTS		:	\$	7,405.00		
TOTAL LABOUR CHARGES		:	\$	5,172.00		
GRAND TOTAL		:	\$	12,577.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian G
Resurveyed
fls.