

## STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number: 63685592

Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

Date Generated : 30/12/2022 User ID : PohSuan

	Section A - Accident Details					
Registration Number	SHF188R					
Case Reference Number	TAX/11/22/2033					
Registration Date	26/12/2019					
Company Type	Strides Taxi Pte Ltd					
Make	ТОУОТА					
Model	PRIUS4FL					
Name of Driver	AW WEE SENG, ZART (HU WEIXING)					
Type of Accident	Head to Rear					
Accident Date and Time	15/11/2022 12:15 PM					
Accident Reported Date and Time	15/11/2022 2:01 PM					
Is Surveyor Required?	Yes					
Survey by						
Vehicle is Towed Back?	No					
Towed Back Date and Time						
Replacement Vehicle issued?	No					
Job Card Number	24116868					
Special Instruction to ARC,if	TP/ REAR PORTION					
Prepared Date and Time	15/11/2022 2:23 PM					
Chassis Number						
Mileage						
Work Shop						
Repair Completion Date and Time						

Section B - Summary of Repair Estimates						
Summary of Repair Estimate	s					
	Quotation from ARC	Adjusted by Surveyor, if applicable				
Total Labour Cost	\$876.00	\$300.00				
Total Spray Cost	\$1,656.00	\$450.00				
Total Spare Part Cost	\$5,275.78	\$1,396.22				
Total Other Cost	\$500.00	\$40.00				
TOTAL COST	\$8,307.78	\$2,186.22 (P/P)				
Lump Sum Total	\$0.00	\$0.00				
Number of Repair Days	9.0	4.0				
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / III				
ARC / Surveyor Sign Off Date	17/11/2022 1:59 PM	17/11/2022 11:43 AM				
Signature		Rosul				
Remarks	Initial 6 days / sup 3 days / total 9 days	part by part repair / Before paint photo ,FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com				



## STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number: 68662672

Date Generated : 30/12/2022 User ID : PohSuan

Section C - Quotation and Accident Invoice Details						
Quotation Number	QN-2212-0091	Invoice Number				
Quotation Date	13.12.2022	Invoice Date				
Invoice Amount		Prepared Date				

Section D - Details of Repair Estimates							
Part 1 - Labour Works							
Job Scope	Quotation from AR	Adjusted by Surveyor, if					
TO REPAIR REAR END PANEL	\$200.00	\$100.00					
TO REPAIR REAR PORTION	\$676.00	\$200.00					
Total Labour	\$876.00	\$300.00					

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO RESPRAY REAR PANEL	\$180.00	\$150.00		
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00		
TO RESPRAY REAR BUMPER	\$378.00	\$200.00		
TO RESPRAY REAR PANEL	\$180.00	\$0.00		
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00		
TO RESPRAY TAIL GATE	\$378.00	\$0.00		
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00		
Total Spray Painting & Panel Beating	\$1,656.00	\$450.00		

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO WASH AND VACUUM	\$60.00	\$0.00		
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00		
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00		
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00		
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00		
Total Other Costs	\$500.00	\$40.00		

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52023- 47030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check	X
		52159- 47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	Replace	√ c
		52462- 47130	PAD, RR BUMPER, RH & LH, 3	2.00	\$12.00	25.00	\$18.00	Replace	Replace	
		52462- 47030	PAD, RR BUMPER, RH & LH,	2.00	\$4.30	25.00	\$6.45	Replace	Replace	
		52462- 47020	PAD, RR BUMPER, RH & LH ,	2.00	\$4.30	25.00	\$6.45	Replace	Replace	
		52461- 47070	PAD, RR BUMPER, CTR	3.00	\$12.00	25.00	\$27.00	Replace	Replace	
		52191- 47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace	Replace	
		52599- 68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X



## **STRIDES Accident Vehicle Repair Estimates**

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/12/2022 User ID : PohSuan

otal				\$6,079.00		\$828.08			
		STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
		STRIDES LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
	47200	LUGGAGE COMPARTMENT		4-00		1000		1	
	75442-		0.00	\$59.10	0.00	\$0.00	Replace	Not Given	X
	47220	LUGGAGE COMPARTMENT		+555	1	15.55	,,		X
	75441-		0.00	\$59.10	0.00	\$0.00	Replace	Not Given	$\dashv_{\checkmark}$
	47170-A1	OUTSIDE GARNISH SUB-	0.00	φ992.30	0.00	φυ.υυ	Neplace	Not Given	X
	76801-		0.00	\$992.30	0.00	\$0.00	Replace	Not Given	
	67005- 47530	TAIL GATE PANEL SUB- ASSY, BACK DOOR	0.00	\$1,238.40	0.00	\$0.00	Replace	Not Given	X
			0.00		0.00	, , , , ,	Replace		X
	47100	BODY LOWER BACK	0.00	\$37.00	0.00	\$0.00	Donland	Not Given	
	58307-		0.00	\$707.10	0.00	\$0.00	Replace	Check	X
	89997- 30100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Check	X
			0.00	\$180.00	0.00	\$0.00	Replace	Check	X
	47010	UNDER CENTER				,		_	X
	47030 66259-	UNDER , LH COVER, REAR FLOOR	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	
	58399-	COVER, REAR FLOOR	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
	47050	UNDER, REAR FLOOR	0.00	φ109.20	0.00	φυ.υυ	Replace	INOL GIVEII	X
	29 58398-	SCREW	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	_
	90189060		0.00	\$2.20	0.00	\$0.00	Replace	Not Given	$\neg_{X}$
	81920- 47030	REAR BUMPER REFLECTOR	0.00	\$42.20	0.00	\$0.00	Replace	Not Given	X
	47030	ASSY, REFLEX, RH				,	'		X
	47070 81910-	LOWER REAR BUMPER REFLECTOR	0.00	\$42.20	0.00	\$0.00	Replace	Not Given	$-\frac{1}{2}$
	52169-	COVER, GUARD RR BUMPER	1.00	\$23.90	25.00	\$17.93	Replace	Replace	
	52453- 47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace	Replace	
	52161- 16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	$\sqrt{r}$
	47080	, - ,				,	•		X
	47080 52592-	SEAL. RR BUMPER . LH	0.00	\$128.00	0.00	\$0.00	Replace	Not Given	
	52591-	SEAL, RR BUMPER , RH	0.00	\$128.00	0.00	\$0.00	Replace	Not Given	-X
	52576- 47060	RETAINER, RR BUMPER, LH	0.00	\$143.60	0.00	\$0.00	Replace	Not Given	X
	47060	RETAINER, RR BUMPER, RH				, , , , ,			X

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023- 47030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		75441- 47220	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace
		75442- 47200	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace
Total					687.70		568.14		

nec ec nec nec

ec

1,396.22

300.00

490.00

2,186.22