

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road

Singapore 159934

Biz. Reg. No.: 199101494Z

GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company

CHINA TAIPING INSURANCE (S) PL

3 ANSON ROAD

#18-00 SPRINGLEAF TOWER

Singapore 079909

Customer Details:

Mr

KANDESAN

S/O RAMASAMY

308 TAMPINES STREET 32

#08-114

Singapore 520308

Document no.

Document date

Customer no.

Customer GST-ID

Dealer

Job order number

Job order date

Service Advisor

14-11-2022

5211001170

200208384E

30001

2022033068/ 1

12-11-2022

YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLU4177U	5G12BZ	30-11-2017	WWWZZZAUZHW122047	Golf 1.2 TLBM 81 TSI D7F	41,825

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
D 169300M2	1k Window Adhesive	2	pcs.	51.44	#1	102.88	110.08
D 00940104	All Purpose Cleaner	1	pcs.	102.88	#1	102.88	110.08
D 00920002	Primer	1	pcs.	30.27	#1	30.27	32.39
D 181802M1	Activator	1	pcs.	26.27	#1	26.27	28.11
D 00950025	Applicator	2	pcs.	11.16	#1	22.32	23.88
5G6827025Q	Rear Trunk Lid	1	pcs.	3,184.78	#1	3,184.78	3,407.71
5G6827505B 9B9	Hood Latch Satin Black	1	pcs.	266.89	#1	266.89	285.57
	BOOT LID LOCK						
5G6827469F FOD	Oper.Mechan.With Micro Sw	1	pcs.	802.61	#1	802.61	858.79
510827861A	Water Drain Hose	1	pcs.	9.54	#1	9.54	10.21
5G6827705E	Gasket	1	pcs.	299.42	#1	299.42	320.38
	BOOT WETHERSTRIP						
5G0945087B	Additional Brake Light W:	1	pcs.	183.08	#1	183.08	195.90
	3RD BRAKELIGHT						
5G0945093AD	Taillight	1	pcs.	317.12	#1	317.12	339.32
	LHS TAILLIGHT INNER						
5G0853687 2ZZ	Inscription Bright Chrome	1	pcs.	89.77	#1	89.77	96.05
	NAME PLATE - GOLF						
5G0853675AR2ZZ	Inscription Bright Chrome	1	pcs.	81.11	#1	81.11	86.79
	NAME PLATE - 180 TSI						
5G6807417APGRU	Cover For Bumper Primed	1	pcs.	1,417.50	#1	1,417.50	1,516.73
5G6807568B 9B9	Rear Diffuser Satin Black	1	pcs.	361.39	#1	361.39	386.69
WHT005263	Rivet	4	pcs.	1.32	#1	5.28	5.65
5G0807305D	Bumper	1	pcs.	750.84	#1	750.84	803.40
	REINFORCEMENT						
5G6807863C	Attachment Strip	1	pcs.	73.18	#1	73.18	78.30
	BUMPER CTR BRACKET						
5G6807393A	Guide Piece		pcs.	43.33	#1	43.33	46.36
	LHR BUMPER BRACKET (UPPER)						
5G6807394A	Guide Piece		pcs.	43.33	#1	43.33	46.36
	RHR BUMPER BRACKET (UPPER)						
5G6807393	Guide Piece		pcs.	43.33	#1	43.33	46.36
	LHR BUMPER BRACKET (SIDE)						
5G6807394	Guide Piece		pcs.	43.33	#1	43.33	46.36
	RHR BUMPER BRACKET (SIDE)						
1K8943021	License Plate Light	2	pcs.	44.37	#1	88.74	94.95
5G0945105	Reflector	1	pcs.	81.02	#1	81.02	86.69
	REFLECTOR LH						
	LABOUR		pcs.	840.00	#1	840.00	898.80
	SPRAY PAINT		pcs.	800.00	#1	800.00	848.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
KANDESAN
S/O RAMASAMY
308 TAMPINES STREET 32
#08-114
Singapore 520308

Document no.
Document date 14-11-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022033068/ 1
Job order date 12-11-2022
Service Advisor YEN MEI WONG


License plate	Model code	First registration	VIN	Model	Mileage
SLU4177U	5G12BZ	30-11-2017	WVWZZZAUZH122047	Golf 1.2 TLBM 81 TSI D7F	41,825

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	REAR NAMBER PLATE 44	1	pcs.	80.00	#1	80.00	85.60
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00
	INCOME VS CHINA TAIPING 3RD PARTY VEHICLE GBL950X D.O.A: 09-11-2022 SURVEY BY:						

Quotation valid till 19-11-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	19,820.21	7%	1,440.61	20,580.21	22,020.82
Total	760.00	19,820.21		1,440.61	20,580.21	22,020.82

Customer



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Handwritten notes:
RAME
Hp 90010068
5 days + 1 day = 6 days
P/P
16/11/22 @ 1410
Rey before part