



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: HO WINNIE			Ref: CS/ASM22011457/Dny3m4 Date: 22/12/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8218B	Veh. Inspected	SLB 7671P	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M04ES1	Excess (\$)	0.00	
Assign From	HO WINNIE	Assign Date	15/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ A180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDD1760422J439544	Colour	GREY	
Odometer	104710 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	CONTINENTAL	5 mm	
L/H Front Tyre	225/45 R17	CONTINENTAL	5 mm	
R/H Rear Tyre	225/45 R17	CONTINENTAL	5 mm	
L/H Rear Tyre	225/45 R17	CONTINENTAL	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/11/2022	Inspection Date	15/11/2022	
Survey held at	ALFRED AUTO SERVICES & SUPPLIES BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	