



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909		Ref: CS/UOI22011461/Uwy3e2 Date: 24/11/2022 Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GY 1588A	Veh. Inspected	SMW 8884M
Policy No.		Coverage (\$)	0.00
Claim No.	M11D00192211	Excess (\$)	0.00
Assign From	KATIE LEE	Assign Date	15/11/2022
2. Vehicle Particulars & Condition			
Make & Model	AUDI A5 SPORTBACK (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WAUZZZF5XMA000508	Colour	GREEN
Odometer	46848 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	PIRELLI	7 mm
L/H Front Tyre	245/40 R18	PIRELLI	7 mm
R/H Rear Tyre	245/40 R18	PIRELLI	7 mm
L/H Rear Tyre	245/40 R18	PIRELLI	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/11/2022	Inspection Date	16/11/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	