



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22011462/Any3q2	
			Date: 06/01/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGW 328B	Veh. Inspected	SLQ 4141T
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2204132/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	15/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A4	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WAUZZZF44HA176483	Colour	BLUE
	Odometer	67825 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	PIRELLI	6 mm
	L/H Front Tyre	225/50 R17	PIRELLI	6 mm
	R/H Rear Tyre	225/50 R17	PIRELLI	6 mm
	L/H Rear Tyre	225/50 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/11/2022	Inspection Date	16/11/2022
	Survey held at	QMO ENGINEERING 10 KAKI BUKIT ROAD 2, #03-18, FIRST EAST CENTRE, SINGAPORE 417868		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	