

Not Withheld
 11 Sep @ 3050h
 Pending After Paint
 3 days

VEHICLE NO: PC8445S

CHASSIS NO: GDH2011020484

MODEL: TOYOTA HIACE 2.8

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
FRONT BUMPER	\$ 7 650.00 ✓
FRONT BUMPER RETAINER LHS	\$ 1 150.00 X
FRONT BUMPER RETAINER RHS	\$ 1 150.00 X
BUMPER TOWING COVER	\$ 1 45.00 ✓
FOG LAMP COVER LHS	\$ 1 60.00 X
FOG LAMP COVER RHS	\$ 1 60.00 X
FRONT GRILLE 568.90	mgm \$ 1,200.00 ✓
FRONT REINFORCEMENT BAR	\$ 1 360.00 ✓
FRONT BONNET	\$ 1 1,030.00 X
TOYOTA EMBLEM	\$ 1 75.00 ✓
FRONT BONNET HINGE LHS	\$ 1 95.00 X
FRONT BONNET HINGE RHS	\$ 1 95.00 X
HEADLAMP LHS	sm \$ 2,102.00 X
HEADLAMP RHS	mgm \$ 2,102.00 ✓
HEADLAMP BRACKET LHS	\$ 1 45.00 X
HEADLAMP BRACKET RHS	\$ 1 45.00 X
FRONT SUPPORT PANEL	\$ 1 780.00 X
AIRCOND CONDENSER	\$ 1 980.00 X
WATER RESERVOIR TANK	\$ 1 290.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25%	\$ 10,314.00
	\$ 2,578.50
	\$ 7,735.50

SPECIAL NETT ITEMS

CARPLATE WITH HOLDER

cm \$ 150.00 45m

FRONT BUMPER CLIPS 1 SET
FRONT GRILLE CLIPS 1 SET

\$ *Ne* 60.00
\$ *Ne* 60.00

Total \$ 270.00

TOTAL PARTS \$ 8,005.50

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)
<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ ⁴⁰⁰ 1,200.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ ⁴⁰⁰ 1,200.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ ²⁰⁰ 100.00
4	To provide anti-rust treatment on affected areas	\$ ^{na} 100.00 X
5	To remove and re-fix front aircond condenser and re-fill gas	\$ ^{na} 200.00 X
6	To remove and re-fix front radiator and re-fill coolant	\$ ^{na} 180.00 X
Labour Total :		\$ 2,980.00
TOTAL (PARTS & LABOUR):		\$ 10,985.50