

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En	Automo	bile CS2/CI	NE2200106	
	LIBERTY INSURA	Ref:		09/0WF22001001/Vm3			
	PTE LTD	& COMPANY INTERNATIONAL		Date:	02/03/2022	14/11/2022	
	A 6 SHENTON WAS SINGAPORE 0688	AY, #19-10 OUE DOWNTOWN2, 09SINGAPORE 068809					
			Code:				
1.	Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected		SLV 4391L		
	Policy No.		Coverage (\$)		0.00		
	Claim No.	1095870/G/KY	Excess (\$)		0.00		
	Assign From	KENNETH YEE	Assign Date		02/03/2022	14/11/2022	
2.		Vehicle Partic	culars & Condition	on			
	Make & Model		c.c		0		
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	-	Steering				
	Brakes		Modification				
	General						
3.		Condition	ons of Tyres				
		Size	Make		Balance		
	R/H Front Tyre				mm		
	L/H Front Tyre				mm		
	R/H Rear Tyre				mm		
	L/H Rear Tyre				mm		
4.	Description of Damages						
5. General Information							
	Accident Date	07/02/2022	Inspection Date	•	02/03/2022		
	Survey held at	CAR CITY AUTO CENTRE PTE	LTD				
		BLK 9006 TAMPINES ST 93 #01-198					
5a.		SINGAPORE 528840 Remarks					
Ju.	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.						
	B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.						