



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22011478/Avy3e2	
			Date: 11/07/2023	
			Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMV 4541J	Veh. Inspected	SLN 7139Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS22/1970	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	15/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA SHUTTLE HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	GP71113869	Colour	BLUE	
Odometer	260926 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/11/2022	Inspection Date	17/11/2022	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 15 MAY 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	