



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22011495/Kwy3e2	
			Date: 14/12/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 8403Z	Veh. Inspected	SMP 2303A	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2204162/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	16/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GB71079112	Colour	METALLIC BLUE	
Odometer	173385 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/11/2022	Inspection Date	17/11/2022	
Survey held at	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	