



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22011496/Any3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 13/02/2023

ATTN: SERENE LIM

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 4773K	Veh. Inspected	SCP 1311B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1197047-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	16/11/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MRHFC1660HT000224	Colour	RED
Odometer	68747 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	MICHELIN	6 mm
L/H Front Tyre	225/45 R18	MICHELIN	6 mm
R/H Rear Tyre	225/45 R18	MICHELIN	6 mm
L/H Rear Tyre	225/45 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/11/2022	Inspect Date / Time	16/11/2022 (03:08 PM)
Survey held at	DETAIL LAB BLK 8 KAKI BUKIT AVE 4 #02-03/04 PREMIER @ KB SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days