



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:WINNIE			Ref: CC4/ASM22011507/Upa3q2 Date: 03/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 3481L	Veh. Inspected	SJU 8148B	
Policy No.	GA529367	Coverage (\$)	0.00	
Claim No.	S2M04EXF	Excess (\$)	0.00	
Assign From		Assign Date	16/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (M)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JHMFD15309S203238	Colour	BLUE	
Odometer	197904 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	CONTINENTAL	7 mm	
L/H Front Tyre	225/45 R17	CONTINENTAL	7 mm	
R/H Rear Tyre	225/45 R17	CONTINENTAL	7 mm	
L/H Rear Tyre	225/45 R17	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/11/2022	Inspection Date	17/11/2022	
Survey held at	SPEEDWERKZ PTE LTD 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	