

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 18 Nov 2022

## **Preliminary Advice**

Vehicle No	: SMZ9096Z	Accident Date	: 29/09/2022
Make	: BMW 320I	Policy No.	: SP2000882639-01
Assignment Date	: 16/11/2022	Excess	: S\$600.00
Date of Inspection	: 17/11/2022	Est. Duration of Repair	: 10 DAYS
Inspection At	: CHIA AUTO SERVICE PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,057.12
Revised Amount	:S\$	11,047.98
Check Items (Estimated)	:S\$	3,744.30
Total	:S\$	14,792.28

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	27,841.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,159.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer agreed to repair the vehicle not more than \$14,000.00
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.