

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 18 Nov 2022

## **Preliminary Advice**

Vehicle No	: SKZ9165G	Accident Date	: 14/11/2022
Make	: HYUNDAI ELANTRA	Policy No.	: SP2000757249-01
Assignment Date	: 17/11/2022	Excess	: S\$600.00
Date of Inspection	: 17/11/2022	Est. Duration of Repair	: 14 DAYS
Inspection At	: VIN'S MOTOR PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,740.00
Revised Amount	:S\$	17,674.00
Check Items (Estimated)	:S\$	9,702.00
Total	:S\$	27,376.00

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	49,000.00
COE / PARF Rebate	:S\$	24,976.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,024.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The Repairer agreed to repair the vehicle not more than \$24,000.00
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.