



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI22011554/Dvy3m4

Date: 24/02/2023

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 8640J	Veh. Inspected	SGN 9928H
Policy No.	D22099240	Coverage (\$)	0.00
Claim No.	D22003617MFCV	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	17/11/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180K	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WDD2040452A337432	Colour	RED
Odometer	182487 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	GOODYEAR	5 mm
L/H Front Tyre	225/40 R18	GOODYEAR	5 mm
R/H Rear Tyre	225/40 R18	GOODYEAR	5 mm
L/H Rear Tyre	225/40 R18	GOODYEAR	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/11/2022	Inspection Date	17/11/2022
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**