

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep. m.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐


: Weekend (\$

) \_\_\_S + RS \_\_\_SI

) Photos

) Others

TOTAL



24/11/22 4/5 @ 8500 informed MR Lee

# LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Sales@Leebrothers.com.sg

not Authorized  
her

17/11/22

2/5 \$ 8500  
5 days

Vehicle Number: SND5803E

Vehicle Model: VOLKSWAGEN T-CROSS

## PARTICULAR

## AMOUNT

QTY

SS

### LIST PRICE

|   |                                 |       |             |   |
|---|---------------------------------|-------|-------------|---|
| 1 | REAR BUMPER -TOP                | Dis   | \$ 1,476.75 | ✓ |
| 1 | REAR BUMPER -CTR                | Dis   | \$ 1,076.72 | ✓ |
| 1 | REAR BUMPER -LOWER              | great | \$ 377.43   | ✓ |
| 1 | REAR BUMPER PDC SENSOR -RH      | Daye  | \$ 241.33   | ✓ |
| 1 | REAR BUMPER PDC SENSOR HOLDER   | her   | \$ 18.60    | ✓ |
| 1 | REAR BUMPER TOW COVER           | 11    | \$ 21.45    | X |
| 1 | REAR BUMPER SIDE GUIDE -RH      | Dis   | \$ 110.25   | ✓ |
| 1 | REAR BUMPER SIDE RETAINER -RH   | Bert  | \$ 116.43   | ✓ |
| 1 | REAR BUMPER TOP GUIDE           | 11    | \$ 190.65   | X |
| 1 | REAR BUMPER REINFORCEMENT       | 11    | \$ 699.73   | X |
| 1 | REAR BUMPER REFLECTOR -RH       | 11    | \$ 181.65   | X |
| 1 | REAR FENDER WHEEL ARCH GARNISH  | Dis   | \$ 481.33   | ✓ |
| 1 | REAR FENDER INNER SHIELD        | 11    | \$ 189.91   | X |
| 1 | REAR FENDER -RH                 | 2     | \$ 1,671.25 | X |
| 1 | FRONT DOOR -RH                  | Body  | \$ 2,318.85 | ✓ |
| 1 | FRONT DOOR PROTECTOR            | wopud | \$ 560.95   | ✓ |
| 1 | FRONT DOOR GLASS OUTER MOULDING | her   | \$ 211.50   | ✓ |
| 1 | FRONT DOOR GLASS RUN CHANNEL    | 11    | \$ 311.45   | X |
| 1 | FRONT DOOR INNER LOCK           | Daye  | \$ 499.13   | ✓ |
| 1 | FRONT DOOR INNER TRIM BOARD     | 11    | \$ 891.96   | X |
| 1 | FRONT DOOR W/STRIP              | her   | \$ 186.93   | ✓ |
| 1 | FRONT DOOR CHECKER              | twi   | \$ 110.25   | ✓ |
| 2 | FRONT DOOR HINGES @\$121.65     | twi   | \$ 243.30   | ✓ |
| 1 | FRONT DOOR PILLAR               | 2     | \$ 243.30   | X |
| 1 | FRONT FENDER -RH                | BUL   | \$ 1,055.90 | ✓ |
| 1 | FRONT FENDER PROTECTOR          | twi   | \$ 581.90   | ✓ |
| 1 | FRONT FENDER WHEEL ARCH GARNISH | 11    | \$ 191.60   | X |
| 1 | FRONT FENDER CHROME MOULDING    | 11    | \$ 399.63   | X |
| 1 | FRONT DOOR CHROME MOULDING      | her   | \$ 121.50   | ✓ |

\$ 14,781.63

LESS 5%

\$ 739.08

\$ 14,042.55



# LEE BROTHERS AUTOMOTIVE PTE. LTD.

Vehicle Number: SND5803E

Vehicle Model: VOLKSWAGEN T-CROSS

## SPECIAL NETT ITEMS

|                                              |   |                  |   |
|----------------------------------------------|---|------------------|---|
| 1 (SET) REAR BUMPER CLIP                     | ✓ | \$ 45.00         | ✓ |
| 1 (SET) REAR FENDER WHEEL ARCH GARNISH CLIP  | ✓ | \$ 80.00         | ✓ |
| 1 (SET) FRONT FENDER WHEEL ARCH GARNISH CLIP | ✓ | \$ 80.00         | ✓ |
| 1 (SET) FRONT FENDER INNER SHIELD CLIP       | ✓ | \$ 65.00         | ✓ |
|                                              |   | <u>\$ 270.00</u> |   |

## LABOUR CHARGES

|                                                          |                    |      |
|----------------------------------------------------------|--------------------|------|
| TO CHECK FRONT & REAR ELECTRICAL WIRING                  | \$ 50.00           | 20   |
| TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR   | \$ 120.00          | 80   |
| TO TUFF KOTE                                             | \$ 120.00          | 50   |
| TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS            | \$ 1,500.00        | 1000 |
| TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS | \$ 1,200.00        | 600  |
|                                                          | <u>\$ 2,990.00</u> |      |

**ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 17,302.55**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-9788.25  
102  
8810.14  
45  
1830