

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

ABWIN
Service Pte Ltd



M9 Automobile Pte Ltd
M9 International Pte Ltd

SUPPLEMENTARY: HQQ000707

TO : INCOME INSURANCE LIMITED
ATTN : MOTOR CLAIM DEPARTMENT

YN8693C
NEW MODERN METAL & PLASTICS PTE. LTD.
202 BEDOK SOUTH AVENUE
1
#01-60
SINGAPORE,
SINGAPORE 469332
CONTACT NO : 68469609

DATE : 13-DEC-2022
MAKE : ISUZU
MODEL : NNR85UH4A
CHASSIS NO : JAANNR85HE7100443
ENGINE NO : 4JJ11S9059
SERVICE ADVISOR : HAZEL
PAGE : 1 OF 1

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
<u>SPECIAL NETT</u>			
1	ADVERTISEMENT STICKER	<i>net</i> 600.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SUB-TOTAL	600.00	0.00
GST - 7 %	42.00	0.00
TOTAL	642.00	0.00

ABWIN SERVICE PTE LTD