

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Nov 2022 19:48	Clim Veh Model Changed		[] Merimen Administrator
2	15 Nov 2022 19:48	Clim Created	Reg No: SKX5735Z. Policy No: 2100443365-06. Acct Date: 2022/11/14. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP1422BF0001	[I] Merimen Administrator
3	17 Nov 2022 16:16	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	17 Nov 2022 16:16	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	17 Nov 2022 16:16	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	17 Nov 2022 16:16	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/11/28	[A] CELINE FONG
7	17 Nov 2022 16:16	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	17 Nov 2022 16:16	Clim Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	17 Nov 2022 16:16	Clim Veh Model Changed	(207019) AUDI A3 SB 1.4 TFSI AMBIENTE (A).	[A] CELINE FONG
10	17 Nov 2022 16:16	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CELINE FONG
11	17 Nov 2022 17:58	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	17 Nov 2022 17:58	Clim Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	17 Nov 2022 17:58	Clim Dtl Modified	JPJ Reg. Date: -> 2015/12/18.	[A] Elaine Kuan Hwa Meen
14	17 Nov 2022 17:58	Clim Details Notified		[A] Elaine Kuan Hwa Meen
15	18 Nov 2022 14:58	Clim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
16	18 Nov 2022 18:00	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/11/28	[A] CELINE FONG
17	18 Nov 2022 18:09	Adj Mandate Request	Cur.Reg:15487.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER ARE ABLE TO REPAIR WITHIN THE NETT VALUE.	[A] CELINE FONG
18	18 Nov 2022 18:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/11/28. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair	[I] Lim, Kok-Chong
19	18 Nov 2022 18:13	Adj Mandate Set	Approved:15487.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong
20	28 Nov 2022 17:36	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/11/28	[A] SHIAU CHAN
21	28 Nov 2022 17:37	Adj Mandate Request	Cur.Reg:36016.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
22	29 Nov 2022 10:37	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/11/28. Mandate Remarks: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Mer	[I] Lim, Kok-Chong
23	29 Nov 2022 10:37	Adj Mandate Set	Approved:20106.00: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong
24	01 Dec 2022 11:57	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/11/28	[A] SHIAU CHAN
25	01 Dec 2022 11:58	Adj Mandate Request	Cur.Reg:36944.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER ARE ABLE TO REPAIR WITHIN THE NETT VALUE. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
26	01 Dec 2022 16:44	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/11/28. Mandate Remarks: Repair Limit set @ \$28K Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair	[I] Lim, Kok-Chong

AUDIT TRAIL				
No.	On	Audit	Remarks	By
27	01 Dec 2022 16:44	Adj Mandate Set	Approved:21034.00:Repair Limit set @ \$28K Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From

Date To

Audit Type

None

Go

ACTIVITY				
No record				

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2870568	17 Nov 2022 17:58:42	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKX5735Z		11.00