

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Nov 2022 19:48	Clm Veh Model Changed		[] Merimen Administrator
2	15 Nov 2022 19:48	Clm Created	Reg No: SKX5735Z. Policy No: 2100443365-06. Acct Date: 2022/11/14. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP1422BF0001	[I] Merimen Administrator
3	17 Nov 2022 16:16	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	17 Nov 2022 16:16	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	17 Nov 2022 16:16	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	17 Nov 2022 16:16	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/11/28	[A] CELINE FONG
7	17 Nov 2022 16:16	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	17 Nov 2022 16:16	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	17 Nov 2022 16:16	Clm Veh Model Changed	(207019) AUDI A3 SB 1.4 TFSI AMBIENTE (A).	[A] CELINE FONG
10	17 Nov 2022 16:16	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CELINE FONG
11	17 Nov 2022 17:58	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	17 Nov 2022 17:58	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	17 Nov 2022 17:58	Clm Dtl Modified	JPJ Reg. Date: -> 2015/12/18.	[A] Elaine Kuan Hwa Meen
14	17 Nov 2022 17:58	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	18 Nov 2022 14:58	Clm Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
16	18 Nov 2022 18:00	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/11/28	[A] CELINE FONG

AUDIT TRAIL

No.	On Audit	Remarks	By
17	18 Nov 2022 18:09 Adj Mandate Request	Cur.Req:15487.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER A RE ABLE TO REPAIR WITHIN THE NETT VALUE.	[A] CELINE FONG
18	18 Nov 2022 18:13 Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/11/28. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repa	[I] Lim, Kok-Chong
19	18 Nov 2022 18:13 Adj Mandate Set	Approved:15487.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong
20	28 Nov 2022 17:36 Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/11/28	[A] SHIAU CHAN
21	28 Nov 2022 17:37 Adj Mandate Request	Cur.Req:36016.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
22	29 Nov 2022 10:37 Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/11/28. Mandate Remarks: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Mer	[I] Lim, Kok-Chong
23	29 Nov 2022 10:37 Adj Mandate Set	Approved:20106.00: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2870568	17 Nov 2022 17:58:42	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKX5735Z		11.00