



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22011585/Uny3q2 Date: 06/12/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBK 8526R	Veh. Inspected	SLS 3812L	
Policy No.	P20611841R01	Coverage (\$)	0.00	
Claim No.	C20018672/JY	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	17/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR HYBRID (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102043044	Colour	BLACK	
Odometer	99945 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50Z R18	TOURADOR	6 mm	
L/H Front Tyre	225/50Z R18	TOURADOR	6 mm	
R/H Rear Tyre	225/50Z R18	TOURADOR	6 mm	
L/H Rear Tyre	225/50Z R18	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2022	Inspection Date	23/11/2022	
Survey held at	EEVOLVEAUTO WORKSHOP LLP 1 Kaki Bukit Avenue 6 #02-25 Autobay @ Kakit Bukit Singapore 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		