



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011589/Kwy3m4 Date: 12/12/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHF 206Y	Veh. Inspected	SNG 873U
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/11/22/2038	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	17/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	MR2BZ3BE900009717	Colour	METALLIC DARK BROWN
	Odometer	25170 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	8 mm
	L/H Front Tyre	225/45 R17	MICHELIN	8 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	8 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/11/2022	Inspection Date	18/11/2022
	Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	