

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 24 Mar 2023

Preliminary Advice

Vehicle No	: SMQ1942G	Accident Date	: 10/11/2022
Make	: AUDI A3	Policy No.	: 1900235910-03
Assignment Date	: 18/11/2022	Excess	: S\$800.00
Date of Inspection	: 15/11/2022	Est. Duration of Repair	: 4
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,810.50 (inclusive supp \$224.50)
Revised Amount	:S\$	11,299.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,299.04
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	108,000.00
COE / PARF Rebate	:S\$	39,638.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,362.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Kindly approve on supplementary