

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0998/2022/EQ
DATE : 14-Nov-22
WIP : 50040

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

3 days - ok - Jy - 06 Feb 23

OWNER'S NAME : MR CHIN LI CHOONG
ADDRESS : 25 WATTEN CLOSE
SINGAPORE 287747

TELEPHONE : HP +65 98789689
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900167067-03
VEHICLE NO : **SGB 7911 G**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 27/09/2019
ENGINE NO : CVK 082422
CHASSIS NO : WAUZZZF4XKA076119
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 09-Nov-22
PLACE OF ACCIDENT : WEST COAST TURN INTO ALEXANDRA ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGB 7911 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$	500.00
4	TO RESPRAY FRONT BUMPER.	\$	900.00	\$	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 3,322.00	\$	1,722.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 7911 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	\$ 1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 144.00	\$ 57.20
7	RADIATOR GRILLE	1	\$ 1,478.00	\$ 1,182.40
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 302.00	
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
11	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00	
12	FRONT BUMPER TOP COVER	1	\$ 143.00	
13	CAUTION SIGN STICKER	1	\$ 16.00	
14	AIR CONDITIONER STICKER	1	\$ 9.00	
15	FRONT BUMPER BRACKET	1	\$ 154.00	
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
17	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	
18	FRONT PARKING AID SEAL RING	4	\$ 10.00	
19	HORN HIGH TONE - LH	1	\$ 134.00	
20	HORN LOW TONE - RH	1	\$ 139.00	
SUB TOTAL SPARE PARTS		:	\$ 7,785.00	\$ 3,141.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 7911 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	3,141.20
21	HORN BRACKET - LH / RH	2	\$ 66.00		
22	HEADLIGHT - LH / RH	2	\$ 16,588.00		
23	LIFT CYLINDER - LH / RH	2	\$ 462.00		
24	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00		
25	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
26	RADIATOR AIR GUIDE - LH / RH INNER	2	\$ 64.00		
27	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 28.00		
28	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 44.00		
29	FRONT NOISE INSULATION	1	\$ 640.00		
30	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
31	SUNDRIES		\$ 400.00	\$	2.88
TOTAL SPARE PARTS		:	\$ 26,265.00	\$	3,204.08
TOTAL LABOUR CHARGES		:	\$ 3,322.00	\$	1,722.00
GRAND TOTAL		:	\$ 29,587.00	\$	4,926.08

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-15/12/22