

Car - n

5/12/22

wip: 50040.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Benji



Hui Pong

AIG - Adrian
- 3 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 7911 G

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
①	FRONT BUMPER <i>torn</i>	1	\$ 2,377.00	✓ <i>fls.</i>
2	FRONT BUMPER FIXING PARTS <i>men</i>	1	\$ 612.00	✗
3	FRONT BUMPER SECURING STRIP - LH / RH <i>men</i>	2	\$ 79.00	✗
4	FRONT BUMPER GRILLE - CENTER <i>men</i>	1	\$ 219.00	✗
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>men</i>	1	\$ 254.00	✗
⑥	FRONT BUMPER AIR GUIDE - LH / RH <i>RH Daged</i>	2	\$ 144.00	✗ <i>72 fls.</i>
7	RADIATOR GRILLE <i>Grilled</i>	1	\$ 1,478.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>men</i>	2	\$ 302.00	✗
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	✗
10	FRONT BUMPER REINFORCEMENT BEAM <i>men</i>	1	\$ 899.00	✗
11	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00	✗
12	FRONT BUMPER TOP COVER <i>men</i>	1	\$ 143.00	✗
13	CAUTION SIGN STICKER	1	\$ 16.00	✗
14	AIR CONDITIONER STICKER <i>men</i>	1	\$ 9.00	✗
15	FRONT BUMPER BRACKET	1	\$ 154.00	✗
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	✗
17	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	✗
18	FRONT PARKING AID SEAL RING	4	\$ 10.00	✗
19	HORN HIGH TONE - LH	1	\$ 134.00	✗
20	HORN LOW TONE - RH	1	\$ 139.00	✗
SUB TOTAL SPARE PARTS			\$ 7,785.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.Adrian Li
Resigned
fls.