



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/01011/2022/EQ
DATE	:	16-Nov-22
WIP	:	50840

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MS MARJORY YEOH
ADDRESS	:	17 BALMEG HILL #05-35 SINGAPORE 119919
TELEPHONE	:	HP +65 97461978
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2100473347-05
VEHICLE NO	:	SLE 429 D
MODEL CODE	:	AUDI S3 SEDAN 2.0 TFSI QU
MODEL YEAR	:	4/7/2016
ENGINE NO	:	CJX 117973
CHASSIS NO	:	WAUZZZ8V3G1098251
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	11-Nov-22
PLACE OF ACCIDENT	:	HOLLAND ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 429 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	✗
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000 ✓
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	1100 ✓
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓ ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 5,402.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 429 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Reg 5</i>	1	\$	3,359.00	+
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$	195.00	+
3	FRONT BUMPER GUIDE SECTION - LH <i>? nn</i>	1	\$	43.00	? X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$	196.00	+
5	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$	1,054.00	+
6	FRONT BUMPER END CAP - LH <i>new</i>	1	\$	91.00	+
7	FRONT FENDER - LH <i>Dented</i>	1	\$	954.00	763.20
8	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$	75.00	X
9	FRONT FENDER BRACKET <i>? nn</i>	1	\$	46.00	? X
10	FRONT FENDER RIVET <i>new</i>	6	\$	23.00	18.24
11	FRONT FENDER BRACE <i>? bent</i>	1	\$	107.00	? 85.60
12	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$	281.00	+
13	HEADLIGHT GAS DISCHARGE LAMP - LH <i>new</i>	1	\$	2,810.00	+
14	FRONT PARKING AID SENSOR <i>new</i>	1	\$	266.00	+
15	FRONT PARKING AID SEAL RING <i>new</i>	4	\$	10.00	+
16	LHS FRONT RIM <i>new</i>	S/N	TBC		+
17	SUNDRIES <i>? nec</i>		\$	400.00	? 5.60
TOTAL SPARE PARTS			:	\$	9,910.00
TOTAL LABOUR CHARGES			:	\$	5,402.00
GRAND TOTAL			:	\$	15,312.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian G

SURVEYED DATE

:

16/11/22

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT