

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	OD/ALLIANZ
Policy No:	SP2001042337-01	Date of Loss:	15/11/2022
Vehicle Reg. No.:	SMJ2219S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ZHANG ZIQI		
Driver:	ZHANG ZIQI		
Make/Model:	MAZDA 6, 2.0 SEDAN STANDARD 2WD (A)	Vehicle Reg. Date:	26/02/2019
Vehicle Colour:	Blue		
Engine No:	PE21255441	Chassis No:	JM6GL1072K0311815
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS	Amount
Parts	5,151.30
Miscellaneous Items	35.00
Labour	1,610.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,796.30
+ GST 7.00% (S\$)	475.74
Nett Amount (S\$)	7,272.04

This claim is handled by: **SHARON CHIONG BENG CHOON**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Nov 2022)
 Parts: 143 MAZDA 6 2.0 SEDAN STANDARD 2WD (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SMJ2219S/18/11/2022 09:46
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER <i>BR</i>	0.00	0.00	*520.00 F
2	1		*1 PC FRT BUMPER RH RETAINER <i>NEL</i>	0.00	0.00	*28.00 F
3	1		*6 PCS FRT BUMPER CLIPS @2/PC <i>NEL</i>	0.00	0.00	*12.00 F
4	1		*1 PC RH HEADLAMP <i>CR</i>	0.00	0.00	*1,380.00 F
5	1		*1 PC RH HEADLAMP LOWER BRACKET ?	0.00	0.00	*25.00 F
6	1		*1 PC FRT GRILLE RH CHROME MOULDING ?	0.00	0.00	*150.00 F
7	1		*1 PC FRT RH FENDER <i>Denx</i>	0.00	0.00	*160.00 F
8	1		*1 PC FRT RH FENDER DUST COVER <i>Denx</i>	0.00	0.00	*68.00 F
9	1		*6 PCS FRT RH FENDER DUST COVER CLIPS @2/PC <i>NEL</i>	0.00	0.00	*12.00 F
10	1		*1 PC FRT RH WHEEL RIM <i>scr</i>	0.00	0.00	*550.00 F
11	1		*1 PC FRT RH LOWER ARM <i>Denx</i>	0.00	0.00	*230.00 F
12	1		*1 PC FRT RH KNUCKLE <i>Denx</i>	0.00	0.00	*185.00 F
13	1		*1 PC FRT RH ABSORBER STRUT <i>Denx</i>	0.00	0.00	*170.00 F
14	1		*1 PC FRT RH ABSORBER STRUT TOP MOUNTING ?	0.00	0.00	*55.00 F
15	1		*1 PC FRT RH ABSORBER STRUT TOP BEARING ?	0.00	0.00	*48.00 F
16	1		*1 PC FRT RH STABILIZER LINK ?	0.00	0.00	*45.00 F
17	1		*2 PCS FRT RH STABILIZER BAR BUSHES @35/PC ?	0.00	0.00	*70.00 F
18	1		*1 PC FRT RH DRIVE SHAFT ?	0.00	0.00	*600.00 F
19	1		*1 PC FRT RH WHEEL HUB ?	0.00	0.00	*250.00 F
20	1		*1 PC STEERING TIE ROD RH ?	0.00	0.00	*65.00 F
21	1		*1 PC STEERING TIE ROD END RH ?	0.00	0.00	*60.00 F

F=Franchise part.

Sub Total (\$\$)	4,683.00
+ Margin on L,N Items 10.00% (\$\$)	468.30
Total Parts (\$\$)	5,151.30

Cheng Hoe Motor Pte Ltd/SMJ2219S/18/11/2022 09:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 UNIT AUTO TRANSMISSION OIL ?	35.00
Sub Total (S\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOWING (BY INSURANCE)	New	0.00
2	REMOVE & REPLACE FRT BUMPER, FENDER, HEADLAMPS, & ATTACHMENTS, PANEL BEAT & REPAIR RH FENDER APRON, INNER BRACKETS, HEADLAMP TOP SUPPORT PANEL & REPLACE DAMAGED BODY PARTS	New	600.00 400
3	REMOVE & REFIX FRT SUSPENSION / UNDERCARRIAGE AND CHECK STEERING	New	250.00 150
4	RESET WHEEL ALIGNMENT	New	80.00 60
5	PUTTY & RESPRAY PAINT ON FRT BUMPER, FRT RH FENDER, FRT TOP PANEL, FRT RH INNER MEMBER	New	680.00 400
Gross Labour Cost (S\$)			1,610.00

Cheng Hoe Motor Pte Ltd/SMJ2219S/18/11/2022 09:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

18/11/22 90097659
L/S After Repair
5 days. 18/11/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: