

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0885/2022/EQ  
**DATE** : 13-Oct-22  
**WIP** : 45907

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/10/2022**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MS SARAH LAU SHEN YI  
**ADDRESS** : 18 PINE GROVE  
#10-02  
SINGAPORE 597594  
**TELEPHONE** : HP +65 82237893  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** :  
**VEHICLE NO** : **SKS 8399 S**  
**MODEL CODE** : AUDI Q2 1.0 TFSI S-TRONIC  
**MODEL YEAR** : 30/7/2020  
**ENGINE NO** : CHZ C33524  
**CHASSIS NO** : WAUZZZGA7KA084781  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 10-Oct-22  
**PLACE OF ACCIDENT** : BLK 19 GHIM MOH ROAD CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 8399 S**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI - LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	x
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	500 ✓
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR.	\$	3,000.00	1100 1650
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	x
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 6,952.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 8399 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH <i>Repr</i>	1	\$ 2,962.00	<i>f</i>
2	REAR OUTER DOOR SEAL - LH <i>2</i>	1	\$ 151.00	<i>f</i>
3	BONDING AGENT	1	\$ 51.00	<i>f</i>
4	CLEANING SOLUTION	1	\$ 74.00	<i>f</i>
5	APPLICATOR	1	\$ 9.00	<i>f</i>
6	REAR DOOR CATCH - LH	1	\$ 134.00	<i>f</i>
7	REAR OUTER DOOR SEAL - LH <i>not on</i>	1	\$ 66.00	<i>f</i>
8	REAR DOOR COVER - LH <i>cut</i>	1	\$ 238.00	<i>190.40</i>
9	REAR DOOR SIDE MEMBER TRIM - LH <i>2</i>	1	\$ 251.00	<i>f</i>
10	REAR WHEEL HOUSING LINER - LH		\$ 220.00	<i>f</i>
11	REAR ALUMINIUM RIM <i>1st</i>	1	\$ 1,002.00	<i>f</i>
12	REAR ALUMINIUM RIM RUBBER VALVE <i>on</i>	1	\$ 4.00	<i>f</i>
13	REAR BUMPER <i>Repr</i>	1	\$ 1,363.00	<i>f</i>
14	REAR BUMPER SPOILER <i>cut</i>	1	\$ 316.00	<i>252.80</i>
15	REAR BUMPER REFLECTOR - LH <i>3 not on</i>	1	\$ 34.00	<i>f</i>
16	REAR BUMPER GUIDE SECTION - LH	1	\$ 60.00	<i>f</i>
17	REAR WHEEL COVER - LH / RH <i>LH cut, RH on</i>	2	\$ 360.00	<i>287.20</i>
18	SUNDRIES <i>nn</i>		\$ 300.00	<i>f x</i>
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 7,595.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 6,952.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 14,547.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian G*  
SURVEYED DATE : *17/11/22*  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : *not authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT