

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0885/2022/EQ
DATE : 13-Oct-22
WIP : 45907

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/10/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS SARAH LAU SHEN YI
ADDRESS : 18 PINE GROVE
#10-02
SINGAPORE 597594
TELEPHONE : HP +65 82237893
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SKS 8399 S**
MODEL CODE : AUDI Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 30/7/2020
ENGINE NO : CHZ C33524
CHASSIS NO : WAUZZZGA7KA084781
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Oct-22
PLACE OF ACCIDENT : BLK 19 GHIM MOH ROAD CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 8399 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	✓
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI - LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	X
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	500. ✓
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR.	\$	3,000.00	1100. ✓
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		: \$	6,952.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 8399 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH <i>Regr</i>	1	\$ 2,962.00	<i>x</i>
2	REAR OUTER DOOR SEAL - LH <i>?</i>	1	\$ 151.00	<i>x</i>
3	BONDING AGENT	1	\$ 51.00	<i>x</i>
4	CLEANING SOLUTION	1	\$ 74.00	<i>x</i>
5	APPLICATOR	1	\$ 9.00	<i>x</i>
6	REAR DOOR CATCH - LH	1	\$ 134.00	<i>x</i>
7	REAR OUTER DOOR SEAL - LH <i>not in</i>	1	\$ 66.00	<i>x</i>
8	REAR DOOR COVER - LH <i>cut</i>	1	\$ 238.00	<i>✓</i>
9	REAR DOOR SIDE MEMBER TRIM - LH <i>?</i>	1	\$ 251.00	<i>x</i>
10	REAR WHEEL HOUSING LINER - LH		\$ 220.00	<i>x</i>
11	REAR ALUMINIUM RIM <i>rip</i>	1	\$ 1,002.00	<i>x</i>
12	REAR ALUMINIUM RIM RUBBER VALVE <i>in</i>	1	\$ 4.00	<i>x</i>
13	REAR BUMPER <i>Regr</i>	1	\$ 1,363.00	<i>x</i>
14	REAR BUMPER SPOILER <i>cut</i>	1	\$ 316.00	<i>✓</i>
15	REAR BUMPER REFLECTOR - LH <i>not in</i>	1	\$ 34.00	<i>✓</i>
16	REAR BUMPER GUIDE SECTION - LH	1	\$ 60.00	<i>x</i>
17	REAR WHEEL COVER - LH / RH <i>LH cut, RH in</i>	2	\$ 360.00	<i>✓</i>
18	SUNDRIES <i>?</i>		\$ 300.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 7,595.00	
TOTAL LABOUR CHARGES		:	\$ 6,952.00	
GRAND TOTAL		:	\$ 14,547.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian G*
SURVEYED DATE : *17/11/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT