

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 21 Nov 2022

**Preliminary Advice**

Vehicle No	: GBJ4415J	Accident Date	: 15/11/2022
Make	: NISSAN NV200 ACENTA	Policy No.	: DMCG22005254
Assignment Date	: 17/11/2022	Excess	: S\$0.00
Date of Inspection	: 18/11/2022	Est. Duration of Repair	: 6
Inspection At	: LKT GROUP PTE LTD (HQ) BLK 3006 UBI ROAD 1, #01 - 384 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,148.46
Revised Amount	:S\$	6,504.48
Check Items (Estimated)	:S\$	5,847.43
Total	:S\$	12,351.91

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	14,439.00

Salvage Value	:S\$
Margin for Repair	:S\$ 40,561.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
  
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
  
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.