



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011632/Aqy3e2	
			Date: 17/02/2023	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6338X	Veh. Inspected	SKV 2795E
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/11/22/2018	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	18/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi outlander	c.c	2360
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JMYXTGF3Wgz001394	Colour	GREEN
	Odometer	123165 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	CONTINENTAL	6 mm
	L/H Front Tyre	225/55 R18	CONTINENTAL	6 mm
	R/H Rear Tyre	225/55 R18	CONTINENTAL	6 mm
	L/H Rear Tyre	225/55 R18	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/11/2022	Inspection Date	21/11/2022
	Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	