

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SKZ8652Z

Make & Model: Mercedes Benz C180

Chassis number: WDD2040462A87779

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper	1	\$ <i>de</i> 1,496.00 ✓
2	Front bumper RH chrome moulding	1	\$ <i>x</i> NN 156.00
3	Front bumper LH chrome moulding	1	\$ <i>x</i> NN 156.00
4	Front bumper LH fog lamp	1	\$ <i>x</i> NN 498.00
5	Front bumper LH fog lamp cover	1	\$ <i>x</i> NN 84.00
6	Front bumper LH fog lamp cover chrome	1	\$ <i>x</i> NN 101.00
7	Front bumper LH side retainer	1	\$ <i>x</i> NN 43.00
8	Front bumper RH side retainer	1	\$ <i>x</i> NN 43.00
9	LH headlamp assy	1	\$ NN <i>x</i> 2,020.00
10	LH front fender	1	\$ <i>ht</i> 891.00 ✓
11	LH front fender emblem	1	\$ <i>rel</i> 72.00 ✓
12	LH front fender splash shield (front)	1	\$ <i>x</i> NN 188.00
13	LH front fender splash shield (rear)	1	\$ <i>x</i> NN 156.00
14	LH front shock absorber	1	\$ <i>x</i> NN 732.00
15	LH front lower arm	1	\$ <i>x</i> NN 641.00
16	LH front knuckle arm	1	\$ <i>f</i> NN 1,140.00
17	LH front wheel bearing	1	\$ <i>x</i> NN 485.00
18	LH front wheel hub	1	\$ <i>x</i> NN 381.00
19	LH front upper arm	1	\$ <i>x</i> NN 742.00
20	LH front tie rod end	1	\$ <i>x</i> NN 156.00
21	Steering rack and pinion	1	\$ <i>x</i> NN 2,745.00
22	LH side mirror assy	1	\$ <i>x</i> NN 1,353.00
23	LH side mirror assy cover	1	\$ <i>x</i> NN 236.00
24	LH front door	1	\$ <i>x</i> NN 2,578.00
25	LH front door upper chrome moulding	1	\$ <i>x</i> NN 165.00
26	LH front door weatherstrip	1	\$ <i>x</i> NN 285.00
27	LH front door lock	1	\$ <i>x</i> NN 405.00
28	LH front door inner trim board	1	\$ <i>x</i> NN 1,231.00
29	LH front door lower rubber seal	1	\$ <i>x</i> NN 62.00
30	LH front door frame black garnish	1	\$ <i>x</i> NN 77.00
31	LH front door frame side black garnish	1	\$ <i>x</i> NN 54.00
32	LH side rocker panel spoiler	1	\$ <i>x</i> NN 708.00

1 Frt LH rim cut ✓

2459

-10%

2213.10

	\$	20,080.00
Parts less 10%	\$	2,008.00
Total	\$	18,072.00

No.	Special Nett Items	Qty	Amount S\$

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Supplementary Estimate

Vehicle number: SKZ8652Z

Make & Model: Mercedes Benz C180

Chassis number:

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Front LH sport rim (Original) CUT	1	\$ 885.00

\$ 885.00

Parts less 10% \$ 88.50

Total \$ 796.50 ✓

No.	Special Nett Items	Qty	Amount S\$

Total: \$ -

No.	Labour and painting	Amount S\$

Total: \$ -

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 796.50

Special Nett: \$ -

Labour: \$ -

Total Amount: \$ 796.50